



North Carolina State Laboratory Public Health  
Environmental Sciences  
Microbiology  
Certificate of Analysis

P.O. Box 28047  
4312 District Drive  
Raleigh, NC 27611-8047  
<http://slph.ncpublichealth.com>  
Phone: 919-733-7308  
Fax: 919-715-8611

Report To:

HENDERSON CO ENVIRONMENTAL HEALTH  
1200 SPARTANBURG HWY - STE 100

HENDERSONVILLE, NC 28792  
EIN:566000307EH

COURIER #: 06-92-01

Name of System:

E H HENDERSON LAND CO LIC  
1246 DANA RD  
HENDERSONVILLE, NC 28792

StarLIMS Sample ID: ES021318-0057001



Collected: 02/12/2018 08:10  
Received: 02/13/2018 08:06

Jonathan Stepp  
Denise Richardson

ES Microbiology ID:  
GPS Number:

Sample Source: Well  
Sampling Point: Well head

Well Permit Number:

Sample Description:  
Comment:

Environmental Microbiology - Colilert Profile

Method: SM 9223B

Test Name: Colilert

| Analyte                   | Test Result | Date       |
|---------------------------|-------------|------------|
| Total Coliform, Colilert  | Absent      | 02/14/2018 |
| <i>E. coli</i> , Colilert | Absent      | 02/14/2018 |

Report Date: 02/15/2018

Reported By: Susan Beasley

Explanations of Coliform Analysis:

If coliform bacteria are **Absent**, the water is considered safe for drinking purpose. If coliform bacteria are **Present**, the water is considered unsafe for drinking purpose. Presence of *E. coli* (bacteria) generally indicates that the water has been contaminated with fecal material. It must be remembered that a water analysis refers only to the sample received and should not be regarded as a complete report on the water supply.