



North Carolina State Laboratory Public Health
Environmental Sciences
Microbiology
Certificate of Analysis

P.O. Box 28047
306 N. Wilmington St.
Raleigh, NC 27611-8047
<http://slph.ncpublichealth.com>
Phone: 919-733-7834
Fax: 919-733-8695

Report To:
HENDERSON CO ENVIRONMENTAL HEALTH
1200 SPARTANBURG HWY - SUITE 1

HENDERSONVILLE, NC 28792
EIN:566000307EH

COURIER #: 06-92-01

Name of System:
ROBERT LANCASTER

1586 PILOT MTN. RD.
HENDERSONVILLE, NC 28792

StarLiMS Sample ID:	ES032212-0087001	Collected:	03/21/2012	08:31	Curt Cline
		Received:	03/22/2012	07:54	Darneice Lyons
ES Microbiology ID:	35258	Sample Source:	Well	Well Permit Number:	
GPS Number:		Sampling Point:	Kitchen		

Sample Description: (Migrant Camp)
Comment:

Environmental Microbiology - Colilert Profile **Method:** SM 9223B

Test Name: Colilert

Analyte	Test Result	Analyst	Date
Total Coliform, Colilert	Absent	Darneice Lyons	03/23/2012
<i>E. coli</i> , Colilert	Absent	Darneice Lyons	03/23/2012

Report Date: 03/26/2012

Reported By: Joy Hayes

Explanations of Coliform Analysis:

If coliform bacteria are **Absent**, the water is considered safe for drinking purpose. If coliform bacteria are **Present**, the water is considered unsafe for drinking purpose. Presence of *E. coli* (bacteria) generally indicates that the water has been contaminated with fecal material. It must be remembered that a water analysis refers only to the sample received and should not be regarded as a complete report on the water supply.