



North Carolina State Laboratory Public Health
Environmental Sciences
Microbiology
Certificate of Analysis

P.O. Box 28047
306 N. Wilmington St.
Raleigh, NC 27611-8047
<http://slph.ncpublichealth.com>
Phone: 919-733-7834
Fax: 919-733-8695

Report To:
HENDERSON CO ENVIRONMENTAL HEALTH
1200 SPARTANBURG HWY - SUITE 1
HENDERSONVILLE, NC 28792
EIN:566000307EH

Name of System:
BRANDON CORNWELL
0 SMITH ROAD
HENDERSONVILLE, NC

StarLiMS Sample ID: **ES051512-0075001**

ES Microbiology ID: **36578**
GPS Number:

Collected: 05/14/2012 09:05
Received: 05/15/2012 08:33

Sample Source: **New Well**
Sampling Point: **Well**

COURIER #: 06-92-01

Sample Description:
Comment:

Environmental Microbiology - Colilert Profile **Method: SM 9223B**

Test Name: Colilert

Analyte	Test Result	Analyst	Date
Total Coliform, Colilert	Absent	Joy Hayes	05/16/2012
<i>E. coli</i> , Colilert	Absent	Joy Hayes	05/16/2012

Report Date: 05/17/2012

Reported By: Joy Hayes

Explanations of Coliform Analysis:

If coliform bacteria are **Absent**, the water is considered safe for drinking purpose. If coliform bacteria are **Present**, the water is considered unsafe for drinking purpose. Presence of *E. coli* (bacteria) generally indicates that the water has been contaminated with fecal material. It must be remembered that a water analysis refers only to the sample received and should not be regarded as a complete report on the water supply.