N.C. Department of Environmental, Health, and Natural Resources Division of Laboratory Services State Laborabory of Public Health P.O.Box 28047 - 306 N. Wilmington Street Raleigh, NC 27611-8047

DO NOT WRITE IN THIS SPACE

BACTERIOLOGICAL ANALYSIS - PUBLIC WATER SYSTEM

Laboratory ID #: Water System ID #: Name of System:	3 7 5 0 1 20-80-069 LKQ Salisbury Inc	County:	Rowan		
ample Type: (1 = Routine; 2 = Repeat; 3 = Replacement; 4 = Plan Approval; 5 = Other)					
Collected on: DATE:	05/16/12	TIME: 08:55		PP / /	
Location where collected:	Outdoor spigot near eyewash				
Location Type:	(1 = Entry Tap; 2 = General Tap; 3 = End Tap; 4 = Source/Intakes; 5 = Other)				
Location Code:	003	Collected By:	R Durha	<u>m</u>	
FOR REPEAT SAMPLE:			FOR REPLACE	MENT SAMPLE:	
Previous Positive Location Code:			Original Sample Type:		
Positive Collection Date:			(1=Routine; 2=Repeat; 3=Plan Approval; 4=Other)		
 Time:			Original Collection Date:		
Proximity:			Time:		
(1 = Same; 2 = Upstream	; 3 = Downstream)				
Mail Results To: MOORESVILLE REC 610 EAST CENTER MOORESVILLE, NC Telephone No. 76 EIN #: 56 60000372	AVENUE 28115 04-663-1699	PWSS IER #: 09-08-06	Type of Supply: Type of Treatme	Community X Non-Community nt: Chlorinated Non-Chlorinated Free Chlorine Residu	al:
	RESULTS			INVALID CODES	
CONTAMINANT Total Coliform Fecal/E. Coli Heterotrophic P.C.	_	ABSENT IN\ X [/ml	/ALID	1) Confluent Growth/No Co 2) TNTC/No Coliform Foun 3) Turbid Culture/No Colifor 4) Over 30 Hours Old 5) Improper Sample or Ana	d rm Found
Repeat Samples Required				Replacement Samples Required	
Date Analysis Begun: Date Analysis Completed: Laboratory Log #:	05/17/12 05/18/12 36668	Natas Causas C			08:30 AM 08:40 AM Beasley
COMMENTS: Special/	Non -compliance, V	vater Source: G	VV	Ollan	- Comment