



North Carolina State Laboratory Public Health
Environmental Sciences
Microbiology
Certificate of Analysis

P.O. Box 28047
306 N. Wilmington St.
Raleigh, NC 27611-8047
<http://slph.ncpublichealth.com>
Phone: 919-733-7834
Fax: 919-733-8695

Report To:	Name of System:		
HENDERSON CO ENVIRONMENTAL HEALTH			RANDY JACKSON
1200 SPARTANBURG HWY - SUITE 100			2119 GILLIAM MTN. RD.
HENDERSONVILLE, NC 28792			HENDERSONVILLE, NC 28792
EIN:566000307EH			
StarLiMS Sample ID:	ES052511-0107001	Collected:	05/24/2011 08:43
		Received:	05/25/2011 07:55
ES Microbiology ID:	27341	Sample Source:	Well
GPS Number:		Sampling Point:	Kitchen
Sample Description:	Migrant Housing		
Comment:			
Environmental Microbiology - Colilert Profile			Method: SM 9223B
Test Name: Colilert			
Analyte	Test Result	Analyst	Date
Total Coliform, Colilert	Absent	Darneice Lyons	05/26/2011
E. coli, Colilert	Absent	Darneice Lyons	05/26/2011

Report Date: 05/31/2011

Reported By: Susan Beasley

Explanations of Coliform Analysis:

If coliform bacteria are **Absent**, the water is considered safe for drinking purpose. If coliform bacteria are **Present**, the water is considered unsafe for drinking purpose. Presence of *E. coli* (bacteria) generally indicates that the water has been contaminated with fecal material. It must be remembered that a water analysis refers only to the sample received and should not be regarded as a complete report on the water supply.