



North Carolina State Laboratory Public Health  
Environmental Sciences  
Microbiology  
Certificate of Analysis

P.O. Box 28047  
4312 District Drive  
Raleigh, NC 27611-8047  
<http://slph.ncpublichealth.com>  
Phone: 919-733-7308  
Fax: 919-715-8611

Report To:  
HENDERSON CO ENVIRONMENTAL HEALTH  
1200 SPARTANBURG HWY - SUITE 1

Name of System:  
JOHN MOTT

HENDERSONVILLE, NC 28792  
EIN:566000307EH

COURIER #: 06-92-01

90 CRABCREEK HGTS  
HENDERSONVILLE, NC 28792

StarLIMS Sample ID: ES060314-0038001



Collected: 06/02/2014 08:43  
Received: 06/03/2014 08:25

Curt Cline  
Angela Heybroek

ES Microbiology ID:  
GPS Number:

Sample Source: Well  
Sampling Point: Well

Well Permit Number:

Sample Description:  
Comment:

Environmental Microbiology - Colilert Profile

Method: SM 9223B

Test Name: Colilert

Analyte	Test Result	Analyst	Date
Total Coliform, Colilert	Absent	Susan Beasley	06/04/2014
<i>E. coli</i> , Colilert	Absent	Susan Beasley	06/04/2014

Report Date: 06/10/2014

Reported By: Susan Beasley

Explanations of Coliform Analysis:

If coliform bacteria are **Absent**, the water is considered safe for drinking purpose. If coliform bacteria are **Present**, the water is considered unsafe for drinking purpose. Presence of *E. coli* (bacteria) generally indicates that the water has been contaminated with fecal material. It must be remembered that a water analysis refers only to the sample received and should not be regarded as a complete report on the water supply.