



North Carolina State Laboratory Public Health  
Environmental Sciences  
Microbiology  
Certificate of Analysis

P.O. Box 28047  
306 N. Wilmington St.  
Raleigh, NC 27611-8047  
<http://slph.ncpublichealth.com>  
Phone: 919-733-7834  
Fax: 919-733-8695

Report To:

HENDERSON CO ENVIRONMENTAL HEALTH

1200 SPARTANBURG HWY - SUITE 100  
HENDERSONVILLE, NC 28792  
EIN:566000307EH

Name of System:

MIKE & TRUDY AKERS

570 LLOYD WILLIAMS RD.  
HENDERSONVILLE, NC 28792

StarLiMS Sample ID: **ES070711-0133001**



Collected: 07/06/2011 08:43

Received: 07/07/2011 09:25

**Curt Cline**  
**Angela Heybroek**

ES Microbiology ID: **28437**

GPS Number:

Sample Source: **New Well**

Sampling Point: **Well**

Well Permit Number:  
**11120101877**

Sample Description:

Comment:

**Environmental Microbiology - Colilert Profile**

**Method: SM 9223B**

**Test Name: Colilert**

Analyte	Test Result	Analyst	Date
Total Coliform, Colilert	Absent	Darneice Lyons	07/08/2011
<i>E. coli</i> , Colilert	Absent	Darneice Lyons	07/08/2011

Report Date: 07/08/2011

Reported By: Susan Beasley

**Explanations of Coliform Analysis:**

If coliform bacteria are **Absent**, the water is considered safe for drinking purpose. If coliform bacteria are **Present**, the water is considered unsafe for drinking purpose. Presence of *E. coli* (bacteria) generally indicates that the water has been contaminated with fecal material. It must be remembered that a water analysis refers only to the sample received and should not be regarded as a complete report on the water supply.