

BACTERIOLOGICAL ANALYSIS - PUBLIC WATER SYSTEM

Laboratory ID #: 37501 County: Union
Water System ID #: 20-90-009
Name of System: Mt Zion Baptist Church
Sample Type: (1 = Routine; 2 = Repeat; 3 = Replacement; 4 = Plan Approval; 5 = Other)
Collected on: DATE: 08/18/09 TIME: 10:35 AM
Location where collected: Well #1 (S01)
Location Type: (1 = Entry Tap; 2 = General Tap; 3 = End Tap; 4 = Source/Intakes; 5 = Other)
Location Code: S01 Collected By: Bill Bass

FOR REPEAT SAMPLE:

Previous Positive Location Code: _____
Positive Collection Date: _____
Time: _____
Proximity:
(1 = Same; 2 = Upstream; 3 = Downstream)

FOR REPLACEMENT SAMPLE:

Original Sample Type:
(1=Routine; 2=Repeat; 3=Plan Approval; 4=Other)
Original Collection Date: _____
Time: _____

Mail Results To:

MOORESVILLE REGIONAL OFFICE PWSS
MOORESVILLE, NC 28115
Telephone No. 704-663-1699

Type of Supply:

Community NTNC
 Non-Community Private

Type of Treatment:

Chlorinated
 Non-Chlorinated
Free Chlorine Residual: _____
Total Chlorine Residual: _____

RESULTS

| CONTAMINANT | METHOD | PRESENT | ABSENT | INVALID |
|--------------------|------------|--------------------------|--------------------------|-------------------------------------|
| Total Coliform | <u>312</u> | <input type="checkbox"/> | <input type="checkbox"/> | <input checked="" type="checkbox"/> |
| Fecal/E. Coli | _____ | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| Heterotrophic P.C. | _____ | _____/ml (number) | | |

Repeat Samples Required

Date Analysis Begun: 08/19/09
Date Analysis Completed: 08/19/09
Laboratory Log #: 8261

INVALID CODES

- 1) Confluent Growth/No Coliform Found
- 2) TNTC/No Coliform Found
- 3) Turbid Culture/No Coliform Found
- 4) Over 30 Hours Old
- 5) Improper Sample or Analysis

Replacement Samples Required

Time Analysis Begun: 08:22 AM
Time Analysis Completed: 08:22 AM
Certified By: Susan Beasley

COMMENTS: <100 ml. of sample received. Please re-sample.