



North Carolina State Laboratory Public Health
Environmental Sciences
Microbiology
Certificate of Analysis

P.O. Box 28047
306 N. Wilmington St.
Raleigh, NC 27611-8047
<http://slph.ncpublichealth.com>
Phone: 919-733-7834
Fax: 919-733-8695

Report To: **HENDERSON CO ENVIRONMENTAL HEALTH** Name of System: **WALTER SHAFER**
1200 SPARTANBURG HWY - SUITE 100 680 BYERS COVE RD.
HENDERSONVILLE, NC 28792 HENDERSONVILLE, NC 28792
EIN:566000307EH COURIER #: 06-92-01

StarLiMS Sample ID: **ES100611-0121001** Collected: 10/05/2011 08:39 **Curt Cline**
 Received: 10/06/2011 09:36 **Angela Heybroek**
ES Microbiology ID: **31029** Sample Source: **New Well** Well Permit Number: **11100101087**
GPS Number: Sampling Point: **Well**

Sample Description:

Comment:

Environmental Microbiology - Colilert Profile Method: SM 9223B

Test Name: **Colilert**

Analyte	Test Result	Analyst	Date
Total Coliform, Colilert	Present	Darneice Lyons	10/07/2011
<i>E. coli</i> , Colilert	Absent	Darneice Lyons	10/07/2011

Report Date: 10/07/2011

Reported By: Susan Beasley

Explanations of Coliform Analysis:

If coliform bacteria are **Absent**, the water is considered safe for drinking purpose. If coliform bacteria are **Present**, the water is considered unsafe for drinking purpose. Presence of *E. coli* (bacteria) generally indicates that the water has been contaminated with fecal material. It must be remembered that a water analysis refers only to the sample received and should not be regarded as a complete report on the water supply.