



North Carolina State Laboratory Public Health  
Environmental Sciences  
Microbiology  
Certificate of Analysis

P.O. Box 28047  
306 N. Wilmington St.  
Raleigh, NC 27611-8047  
<http://slph.ncpublichealth.com>  
Phone: 919-733-7834  
Fax: 919-733-8695

Report To:

HENDERSON CO ENVIRONMENTAL HEALTH

1200 SPARTANBURG HWY - SUITE 100  
HENDERSONVILLE, NC 28792  
EIN:566000307EH

Name of System:

TYLER & SARAH CHEPOLIS

1118 HOOPERS CREEK RD.  
FLETCHER, NC 28732

COURIER #: 06-92-01

StarLIMS Sample ID: ES111711-0054001



Collected: 11/16/2011 08:58

Received: 11/17/2011 08:52

Curt Cline

Angela Heybroek

ES Microbiology ID: 32117

GPS Number:

Sample Source: New Well

Sampling Point: Well

Well Permit Number:

11120106587

Sample Description:

Comment:

Environmental Microbiology - Colilert Profile

Method: SM 9223B

Test Name: Colilert

Analyte	Test Result	Analyst	Date
Total Coliform, Colilert	Absent	Dameice Lyons	11/18/2011
<i>E. coli</i> , Colilert	Absent	Dameice Lyons	11/18/2011

Report Date: 11/21/2011

Reported By: Susan Beasley

Explanations of Coliform Analysis:

If coliform bacteria are **Absent**, the water is considered safe for drinking purpose. If coliform bacteria are **Present**, the water is considered unsafe for drinking purpose. Presence of *E. coli* (bacteria) generally indicates that the water has been contaminated with fecal material. It must be remembered that a water analysis refers only to the sample received and should not be regarded as a complete report on the water supply.