Report to: Blair Murray			Name of System: Holly Ridge Golf Course				
WINSTON SALEM REGIONAL 450 WEST HANES MILL RD STE 30 Winston Salem, NC 27105							
EIN: 566000372X	Delivery: NC C	Courier				Randolph County	
StarLiMS ID: ES180906-0065	Date Collected: Date Received:	09/05/2018 09/06/2018	Time Collected: Time Received:	13:15 09:01	By: By:	Blair Murray Angela Heybroek	
Vater System ID: 02-76-646 Facility ID:	System Type:	NTNC	Water Source: Sample Type:	Ground Water Special/Non-Compliance			
Sample Location: Women's bathro Disinfectant Used:	om Location Type: Free Chlorine:		Location Code: Total Chlorine:	WR1			
Comments:							
PWS - Colilert Profile					Μ	lethod: SM 9223B	
Analyte	Test Result	Unit	Conclusion		D	Date Tested	
Total Coliform E. coli	Absent Absent					9/06/2018 9/06/2018	

Report Date: 09/07/2018

Reported By: **Susan Beasley** 

If coliform bacteria are Absent, the water is considered safe for drinking purpose. If coliform bacteria are Present, the water is considered unsafe for drinking purpose. Presence of E. coli (bacteria) generally indicates that the water has been contaminated with fecal material. It must be remembered that a water analysis refers only to the sample received and should not be regarded as a complete report on the water supply.

4312 District Drive MSC 1918 Raleigh, NC 27699-1918

http://slph.ncpublichealth.com Phone: 919-733-7308 Fax: 919-715-8611

**FINAL REPORT** 

# North Carolina State Laboratory of Public Health

**Environmental Sciences** 

**Microbiology** 

# **Certificate of Analysis**

### **Explanations of Coliform Analysis:**

