



North Carolina State Laboratory of Public Health  
*Environmental Sciences*  
**Microbiology**  
**Certificate of Analysis**

4312 District Drive  
MSC 1918  
Raleigh, NC 27699-1918  
<http://slph.ncpublichealth.com>  
Phone: 919-733-7308  
Fax: 919-715-8611

**FINAL REPORT**

Report to: TRENTON HILL

Name of System:

**HENDERSON CO ENVIRONMENTAL HEALTH**  
1200 SPARTANBURG HWY - STE 100  
Hendersonville, NC 28792

**Joshua Gossett**  
133 Walnut Valley Ln

EIN: 566000307EH

Delivery: UPS

Henderson County

StarLiMS ID: **ES210720-0063**

Date Collected: 07/19/2021

Time Collected: 08:15

By:

Date Received: 07/20/2021

Time Received: 10:51

By: Angela Heybroek

Sample Source: New Well

Sampling Point:

Sample Type: Raw

GPS No.

Treatment:

Well Permit No.

Comment:

**Colisure Profile**

**Method: SM 9223B**

| Analyte        | Test Result | Unit | Conclusion | Date Tested |
|----------------|-------------|------|------------|-------------|
| Total Coliform | Absent      |      |            | 07/20/2021  |
| E. coli        | Absent      |      |            | 07/20/2021  |

Report Date: 07/21/2021

Reported By: **KPLEMMONS**

**Explanations of Coliform Analysis:**

If coliform bacteria are **Absent**, the water is considered safe for drinking purpose. If coliform bacteria are **Present**, the water is considered unsafe for drinking purpose. Presence of *E. coli* (bacteria) generally indicates that the water has been contaminated with fecal material. It must be remembered that a water analysis refers only to the sample received and should not be regarded as a complete report on the water supply.