



North Carolina State Laboratory Public Health  
Environmental Sciences  
Microbiology  
Certificate of Analysis

P.O. Box 28047  
306 N. Wilmington St.  
Raleigh, NC 27611-8047  
<http://slph.ncpublichealth.com>  
Phone: 919-733-7834  
Fax: 919-733-8695

Report To:

HENDERSON CO ENVIRONMENTAL HEALTH  
1200 SPARTANBURG HWY - SUITE 1

HENDERSONVILLE, NC 28792  
EIN:566000307EH

COURIER #: 06-92-01

Name of System:

CABIN DREAM HOMES, INC  
85 DREAMWORKS CT  
HENDERSONVILLE, NC 28792

StarLIMS Sample ID: ES032712-0054001



Collected: 03/26/2012 08:36  
Received: 03/27/2012 08:27

Curt Cline  
Angela Heybroek

ES Microbiology ID: 35358  
GPS Number:

Sample Source: New Well  
Sampling Point: Well

Well Permit Number:  
11100111691

Sample Description:  
Comment:

Environmental Microbiology - Colilert Profile

Method: SM 9223B

Test Name: Colilert

Analyte	Test Result	Analyst	Date
Total Coliform, Colilert	Present	Joy Hayes	03/28/2012
<i>E. coli</i> , Colilert	Absent	Joy Hayes	03/28/2012

Report Date: 04/03/2012

Reported By: Susan Beasley

Explanations of Coliform Analysis:

If coliform bacteria are **Absent**, the water is considered safe for drinking purpose. If coliform bacteria are **Present**, the water is considered unsafe for drinking purpose. Presence of *E. coli* (bacteria) generally indicates that the water has been contaminated with fecal material. It must be remembered that a water analysis refers only to the sample received and should not be regarded as a complete report on the water supply.