



North Carolina State Laboratory Public Health  
Environmental Sciences  
Microbiology  
Certificate of Analysis

P.O. Box 28047  
4312 District Drive  
Raleigh, NC 27611-8047  
<http://slph.ncpublichealth.com>  
Phone: 919-733-7834  
Fax: 919-733-8695

Report To:

HENDERSON CO ENVIRONMENTAL HEALTH  
1200 SPARTANBURG HWY - SUITE 1

HENDERSONVILLE, NC 28792  
EIN:566000307EH

COURIER #: 06-92-01

Name of System:

PATRICK LANCASTER (MIGRANT HOUSE)  
1586 PILOT MTN. RD.  
HENDERSONVILLE, NC 28792

StarLIMS Sample ID: ES052213-0100001



Collected: 05/21/2013 08:38

Received: 05/22/2013 09:25

Curt Cline  
Susan Beasley

ES Microbiology ID:  
GPS Number:

Sample Source: Well  
Sampling Point: Kitchen

Well Permit Number:

Sample Description:  
Comment:

Environmental Microbiology - Colilert Profile

Method: SM 9223B

Test Name: Colilert

| Analyte                   | Test Result | Analyst    | Date       |
|---------------------------|-------------|------------|------------|
| Total Coliform, Colilert  | Absent      | HLBRASWELL | 05/23/2013 |
| <i>E. coli</i> , Colilert | Absent      | HLBRASWELL | 05/23/2013 |

Report Date: 05/24/2013

Reported By: Susan Beasley

Explanations of Coliform Analysis:

If coliform bacteria are **Absent**, the water is considered safe for drinking purpose. If coliform bacteria are **Present**, the water is considered unsafe for drinking purpose. Presence of *E. coli* (bacteria) generally indicates that the water has been contaminated with fecal material. It must be remembered that a water analysis refers only to the sample received and should not be regarded as a complete report on the water supply.