



North Carolina State Laboratory Public Health  
Environmental Sciences  
Microbiology  
Certificate of Analysis

P.O. Box 28047  
4312 District Drive  
Raleigh, NC 27611-8047  
<http://slph.ncpublichealth.com>  
Phone: 919-733-7308  
Fax: 919-715-8611

Report To:  
**HENDERSON CO ENVIRONMENTAL HEALTH**  
**1200 SPARTANBURG HWY - STE 100**

Name of System:  
**CALVIN RUBY**  
**1662 PILOT MTN. RD.**

**HENDERSONVILLE, NC 28792**  
**EIN:566000307EH**

COURIER #: 06-92-01

StarLIMS Sample ID: **ES060716-0095001**



Collected: 06/06/2016 09:00  
Received: 06/07/2016 08:26

**Curt Cline**  
**Susan Beasley**

ES Microbiology ID:  
GPS Number:

Sample Source: **New Well**  
Sampling Point: **well tap**

Well Permit Number:  
**1510016237**

Sample Description:  
Comment:

**Environmental Microbiology - Colilert Profile**

Method: SM 9223B

Test Name: **Colilert**

Analyte	Test Result	Analyst	Date
Total Coliform, Colilert	Absent	Darneice Owens	06/08/2016
<i>E. coli</i> , Colilert	Absent	Darneice Owens	06/08/2016

Report Date: 06/09/2016

Reported By: **Susan Beasley**

**Explanations of Coliform Analysis:**

If coliform bacteria are **Absent**, the water is considered safe for drinking purpose. If coliform bacteria are **Present**, the water is considered unsafe for drinking purpose. Presence of *E. coli* (bacteria) generally indicates that the water has been contaminated with fecal material. It must be remembered that a water analysis refers only to the sample received and should not be regarded as a complete report on the water supply.