N.C. Department of Environmental, Health, and Natural Resources Division of Laboratory Services State Laborabory of Public Health P.O.Box 28047 - 306 N. Wilmington Street Raleigh, NC 27611-8047

DO NOT WRITE IN THIS SPACE

BACTERIOLOGICAL ANALYSIS - PUBLIC WATER SYSTEM

Laboratory ID #:	<u>37501</u>	County:	Caswell		
Water System ID #:	30-17-038	_			
Name of System:	Christmas Cafe'				
Sample Type: 5 (1 = Routine; 2 = Repeat; 3 = Replacement; 4 = Plan Approval; 5 = Other)					
Collected on: DATE:	06/22/10	TIME: 11:	00 AM		
Location where collected:	Compartment Sir	nk			
Location Type:	1 = Entry Tap	; 2 = General Ta	ap; 3 = End Tap; 4 = S	Source/Intakes; 5 = Other)	
Location Code:	E01	Collected By	/: David Re	<u>yes</u>	
FOR REPEAT SAMPLE:			FOR REPLACE	MENT SAMPLE:	
Previous Positive Loc		Origina	al Sample Type:		
Positive Collection Da		_	utine; 2=Repeat; 3=Plan Approval;	4=Other)	
Time:			Original Collection Date:		
Proximity:			Time:		
(1 = Same; 2 = Upstrear	n; 3 = Downstream)				_
Mail Results To:			Type of Supply:		
WINSTON SALEM WINSTON SALEM, Telephone No.		E PWSS	Type of Treatme	Non-Community	
	RESULTS			INVALID CODES	
CONTAMINANT METHOD PRESENT ABSENT INVALID Total Coliform 9223B X			 Confluent Growth/No Coliform Found TNTC/No Coliform Found Turbid Culture/No Coliform Found Over 30 Hours Old Improper Sample or Analysis 		
Repeat Samples Required				Replacement Samples Required	
Date Analysis Begun:	06/23/10			Time Analysis Begun:	07:58 AM
Date Analysis Completed:	06/24/10			Time Analysis Completed:	09:15 AM
Laboratory Log #:			Certified By: Susan I	Beasley	
COMMENTS: Location	n Code: E01, Wate	Source: GW		Tream	Beasley