N.C. Department of Environmental, Health, and Natural Resources Division of Laboratory Services State Laborabory of Public Health P.O.Box 28047 - 306 N. Wilmington Street Raleigh, NC 27611-8047

DO NOT WRITE IN THIS SPACE

BACTERIOLOGICAL ANALYSIS - PUBLIC WATER SYSTEM

Laboratory ID #: Water System ID #:	37501 03-26-244	County:	Cumberland	-		
Name of System:	Speranza Mobile Home Park					
Sample Type: [5] (1 = Routine; 2 = Repeat; 3 = Replacement; 4 = Plan Approval; 5 = Other						
Collected on: DATE:	06/23/09 TIME: 14:35 PM					
ocation where collected: 1736 Easterling Dr Kitchen sink						
Location Type:	5 (1 = Entry Tap;	2 = General	Tap; 3 = End Tap	o; 4 = Source/Intakes; 5 = Other)		
Location Code:		Collected I	By: Keit	th Puckett		
FOR REPEAT SAMPLE:			FOR REPLACEMENT SAMPLE:			
Previous Positive Location Code:			(Original Sample Type:		
Positive Collection Date:		(1=Routine; 2=Repeat; 3=Plan Approval; 4=Other)				
Time:		Original Collection Date:				
Proximity:		Time:				
(1 = Same; 2 = Upstream	3 = Downstream)				_	
Mail Results To:			Type of S	upply:		
FAYETTEVILLE REC 225 GREEN STREET FAYETTEVILLE, 28 Telephone No. 9 ²	Г	PWSS	Type of T	Non-Community P	TNC rivate 	
	RESULTS			INVALID CODES		
CONTAMINANT METHO Total Coliform 312 Fecal/E. Coli Heterotrophic P.C.	DD PRESENT (number)	ABSENT X /ml	INVALID	 Confluent Growth/No Colifor TNTC/No Coliform Found Turbid Culture/No Coliform Over 30 Hours Old Improper Sample or Analys 	Found	
Repeat Samples Required				Replacement Samples Required		
Date Analysis Begun:	06/24/09			Time Analysis Begun:	08:29 AM	
Date Analysis Completed:	06/25/09			Time Analysis Completed:	11:10 AM	
Laboratory Log #:	6275			Certified By: Susan B	easley	
COMMENTS:						