



North Carolina State Laboratory Public Health

Environmental Sciences

Microbiology

Certificate of Analysis

P.O. Box 28047
306 N. Wilmington St.
Raleigh, NC 27611-8047
<http://slph.state.nc.us>
Phone: 919-733-7834
Fax: 919-733-8695

Report To:**HENDERSON CO ENVIRONMENTAL HEALTH****1200 SPARTANBURG HWY - SUITE 100
HENDERSONVILLE, NC 28792****Name of System:****RICHARD & LINDA ETT****1570 TRAMMEL GAP RD.
SALUDA, NC**StarLIMS Sample ID: **ES062910-0051001**

Collected: 06/28/2010 08:37

Received: 06/29/2010 08:48

Curt Cline**Angela Heybroek**ES Microbiology ID: **18031**

GPS Number:

Sample Source: **New Well**Sampling Point: **Side tap**

Well Permit Number:

09120108644

Sample Description:

Comment:

Environmental Microbiology - Colilert Profile**Method:** SM 9223B**Test Name: Colilert**

Analyte	Test Result	Analyst	Date
Total Coliform, Colilert	Absent	Dameice Lyons	06/30/2010
<i>E. coli</i> , Colilert	Absent	Dameice Lyons	06/30/2010

Report Date: 07/06/2010**Reported By:** Susan Beasley**Explanations of Coliform Analysis:**

If coliform bacteria are **Absent**, the water is considered safe for drinking purpose. If coliform bacteria are **Present**, the water is considered unsafe for drinking purpose. Presence of *E. coli* (bacteria) generally indicates that the water has been contaminated with fecal material. It must be remembered that a water analysis refers only to the sample received and should not be regarded as a complete report on the water supply.