BACTERIOLOGICAL ANALYSIS - PUBLIC WATER SYSTEM

Laboratory ID #: Water System ID #: Name of System:		<u>3 7 5 0 1</u> 04-96-010 City of Goldsbord	County:	Wayı	10			
Sample Type:	ŕ	 (1 = Routine; 2 = Repeat; 3 = Replacement; 4 = Plan Approval; 5 = Other) 						
		 08/14/13	TIME: 1		· · ·		,	
Location where colle	-	Center Holly Tanl						
Location Type:	Ì	(1 = Entry Tap;		Tap; 3 = End	Tap; 4 = Sourc	ce/Intakes; 5 = 0	Other)	
Location Code:	·		Collected		Joey White		,	
	-			·	•			
FOR REPEAT SAMPLE:				FOR REPLACEMENT SAMPLE:				
Previous Positive Location Code:					Original Sa	ample Type:		
Positive Colle	(1=Routine; 2=Repeat; 3=Plan Approval; 4=Other)							
		Original Collection Date:						
Proximity:								
	 Upstream; 3	3 = Downstream)						
	NGTON S ON, NC 2 No. 252	29466481	9WSS IER #: 16-(Туре	of Supply:	Free Chlo	nity	
			IN	IVALID COD	ES			
CONTAMINANT METHOD PRESENT ABSE Total Coliform 9223B Image: Colimon state st					 Confluent Growth/No Coliform Found TNTC/No Coliform Found Turbid Culture/No Coliform Found Over 30 Hours Old Improper Sample or Analysis 			
Repeat Samples Required						Replacement Samples Required		
Date Analysis Begun:08/15/13						Time Analysis Begun: 08:30 AM		
Date Analysis Completed: 08/16/13					Ti	Time Analysis Completed: 09:30 AM		
Laboratory Log #:					C	ertified By:		Beasley
COMMENTS:	<u>Special / N</u> Chloramir	Non-compliance (S	SP), Water (Source: SW,	Disinfectant I	Jsed:	Tream	Baaley