N.C. Department of Environmental, Health, and Natural Resources Division of Laboratory Services State Laborabory of Public Health P.O.Box 28047 - 306 N. Wilmington Street Raleigh, NC 27611-8047

DO NOT WRITE IN THIS SPACE

BACTERIOLOGICAL ANALYSIS - PUBLIC WATER SYSTEM

Laboratory ID #: Water System ID #:	37501 20-90-009	County:	Union	<u> </u>		
Name of System:	Mt Zion Baptist Church					
Sample Type: 5 (1 = Routine; 2 = Repeat; 3 = Replacement; 4 = Plan Approval; 5 = Other)						
Collected on: DATE:	08/18/09	TIME: 1	1:00 AM			
Location where collected:	501 well					
Location Type:	4 (1 = Entry Tap	; 2 = General	Tap; 3 = End T	ap; 4 = Source/Intakes; 5 = Other)		
Location Code:	S01	Collected	Ву:	Bill Bass		
FOR REPEAT SAMPLE:			FOR RI	EPLACEMENT SAMPLE:		
Previous Positive Loca			Original Sample Type:			
Positive Collection Dat		(1=Routine; 2=Repeat; 3=Plan Approval; 4=Other)				
Tim		Original Collection Date:				
Proximity:			Time:			
(1 = Same; 2 = Upstream	n; 3 = Downstream)					
Mail Results To: Type of Supply:						
MOORESVILLE NO		PWSS	Tuno of	Non-Community	NTNC Private	
MOORESVILLE, NC Telephone No. 7	O4-663-1699		i ype oi	Treatment: Chlorinated X Non-Chlorinated Free Chlorine Residua Total Chlorine Residua	-	
	RESULTS			INVALID CODES		
CONTAMINANT METHOD PRESENT ABSTACTION Total Coliform 312 X			INVALID	2) TNTC/No Coliform Found3) Turbid Culture/No Coliforr4) Over 30 Hours Old	 Confluent Growth/No Coliform Found TNTC/No Coliform Found Turbid Culture/No Coliform Found Over 30 Hours Old Improper Sample or Analysis 	
Repeat Samples Required				Replacement Samples R	Replacement Samples Required	
Date Analysis Begun: 08/19/09				Time Analysis Begun:	08:22 AM	
Date Analysis Completed: 08/20/09				Time Analysis Completed:	09:30 AM	
Laboratory Log #:	8262			Certified By: Susan I	Certified By: Susan Beasley	
COMMENTS:						