N.C. Department of Environmental, Health, and Natural Resources
Division of Laboratory Services
State Laborabory of Public Health
P.O.Box 28047 - 4312 District Drive

Raleigh, NC 27611-8047 919-733-7308

DO NOT WRITE IN THIS SPACE

## **BACTERIOLOGICAL ANALYSIS - PUBLIC WATER SYSTEM**

Laboratory ID #:	<u>37501</u>	County:	Yadkin			
Water System ID #:	02-99-403					
Name of System:	Bethel Baptist Church					
Sample Type: (1 = Routine; 2 = Repeat; 3 = Replacement; 4 = Plan Approval; 5 = Other)						
Collected on: DATE:	10/07/15	TIME: <b>08:55</b>	AM			
Location where collected:	Kitchen sink					
Location Type:	(1 = Entry Tap	; 2 = General Tap;	3 = End Tap; 4 =	Source/Intakes; 5 = Other)		
Location Code:	E01	Collected By:	Blair Mu	ırray		
FOR REPEAT SAMPLE:			FOR REPLAC	EMENT SAMPLE:		
Previous Positive Location Code:			Original Sample Type:			
Positive Collection Da		(1=Routine; 2=Repeat; 3=Plan Approval; 4=Other)				
Time:			Original Collection Date:			
Proximity:				 Time		
(1 = Same; 2 = Upstream	m; 3 = Downstream)					
Mail Results To:			Type of Supply	<i>y</i> :		
WINSTON SALEM	REGIONAL OFFI	CE PWSS		Community [	NTNC	
WINSTON SALEM,	NC 27107-2241		Type of Treatn			
Telephone No. 336-771-5000 Non-Chlorinated					ed	
-		NED #. 42 45 0	4	Free Chlorine Resid	lual:	
EIN #: 56 6000372	AA COUR	RIER #: 13-15-0	ı	Total Chlorine Resid	dual:	
	RESULTS			INVALID CODES		
CONTAMINANT METH	OD PRESENT	ABSENT IN	VALID	1) Confluent Growth/No C	Coliform Found	
Total Coliform 9223B X				2) TNTC/No Coliform Found		
Fecal/E. Coli				Turbid Culture/No Coliform Found     Over 30 Hours Old		
Heterotrophic P.C.	<del></del>	/ml		5) Improper Sample or An	nalysis	
	(number	)		, , , , ,	•	
Repeat Samples Required				Replacement Samples Required		
Date Analysis Begun: 10/08/15				Time Analysis Begun:	08:25 AM	
Date Analysis Completed: 10/09/15				Time Analysis Completed	08:40 AM	
Laboratory Log #:					n Beasley	
COMMENTS: Special.	/Non-compliance (SP)	, System Type:TN0	C, Water Source: 0	3W The	en Basley	