BACTERIOLOGICAL ANALYSIS - PUBLIC WATER SYSTEM

Laboratory ID #: Water System ID #: Name of System:	<u>3 7 5 0 1</u> 01-95-536 Country Retreat	County: _	Watau	ga		
Sample Type:	5 (1 = Routine; 2	(1 = Routine; 2 = Repeat; 3 = Replacement; 4 = Plan Approval; 5 = Other)				
Collected on: DATE: <u>10/08/13</u> TIME: <u>09:55 AM</u>						
Location where collected:	_					
Location Type:	(1 = Entry Tap	; 2 = General T	ap; 3 = End	Tap; 4 = Source/Intakes; 5 = Other)		
Location Code:		Collected B	y:	Blair Murray		
FOR REPEAT SAMPLE:			FOR F	REPLACEMENT SAMPLE:		
Previous Positive Location Code:			Original Sample Type:			
Positive Collection Date:			(1=Routine; 2=Repeat; 3=Plan Approval; 4=Other)			
Tim		Original Collection Date:				
Proximity:				Time:		
(1 = Same; 2 = Upstrear	n; 3 = Downstream)					
Mail Results To: WINSTON SALEM	NC 27107-2241	E PWSS		of Supply:		
Telephone No. 336-771-5000 Image: Non-Chlorinated Free Chlorine Residual: Free Chlorine Residual:						
EIN #: 56 6000372 XX COURIER #: 13-15-01					Total Chlorine Residual:	
	RESULTS			INVALID CODES		
CONTAMINANT METHOD PRESENT ABSENT INVALID Total Coliform 9223B Image: Colimon for the second				2) TNTC/No Coliform 3) Turbid Culture/No 4) Over 30 Hours Old	 Confluent Growth/No Coliform Found TNTC/No Coliform Found Turbid Culture/No Coliform Found Over 30 Hours Old Improper Sample or Analysis 	
Repeat Samples Required				Replacement San	Replacement Samples Required	
Date Analysis Begun:10/09/13				Time Analysis Begun	08:55 AM	
Date Analysis Completed:	10/10/13			Time Analysis Compl	eted: 09:20 AM	
Laboratory Log #:					usan Beasley	
	/ Non-compliance (Гуре: ТNC,	Water Source: 7	Trean Baasley	