N.C. Department of Environmental, Health, and Natural Resources
Division of Laboratory Services
State Laborabory of Public Health
P.O.Box 28047 - 4312 District Drive
Raleigh, NC 27611-8047
919-733-7308

DO NOT WRITE IN THIS SPACE

BACTERIOLOGICAL ANALYSIS - PUBLIC WATER SYSTEM

Laboratory ID #: Water System ID #:	_	<u>7 5 0 1</u> 2-01-010	County:	ALAMAN	NCE				
Name of System:	C	CITY OF BURLINGTON							
Sample Type: 5 (1 = Routine; 2 = Repeat; 3 = Replacement; 4 = Plan Approval; 5 = Other)									
Collected on:	llected on: DATE: 10/17/17 TIME: 09:53 AM								
Location where colle	collected: SAMPLE STATION @ 124 MEBANE STREET								
Location Type:	Ī	1 = Entry Tap	; 2 = General	Tap; 3 = End T	ap; 4 = Sou	rce/Intakes; 5 =	Other)		
Location Code:	<u>0</u>	01	Collected	By: i	Rodney Da	ırr			
FOR REPEAT SAMI	PLE:			FOR R	EPLACEM	ENT SAMPLE	Ē:		
Previous Positive Location Code:					Original Sample Type:				
Positive Collection Date:					(1=Routine; 2=Repeat; 3=Plan Approval; 4=Other)				
Time:					Original Collection Date:				
Proximity:						Tim	е		
(1 = Same; 2 =	: Upstream; 3	= Downstream)							
Mail Results To:				Туре о	f Supply:				
WINSTON S	SALEM RE	GIONAL OFFIC	E PWSS			X Community	,	NTNC	
450 WEST H	HANES MIL	L RD STE 300)		Ī	Non-Comm	nunity	Private	
WINSTON S	SALEM, NC	27105		Type o	f Treatmen	t: \square Cr	lorinated		
Telephone I		7769800				=	n-Chlorinated		
EIN #: 566000372X COURIER				15-01			lorine Residua Ilorine Residua		
RESULTS						INVALID CO	DES		
CONTAMINANT METHOD PRESENT ABSENT IN Total Coliform 9223B X X Fecal/E. Coli 9223B X Heterotrophic P.C. /ml (number)				INVALID		 Confluent Growth/No Coliform Found TNTC/No Coliform Found Turbid Culture/No Coliform Found Over 30 Hours Old Improper Sample or Analysis 			
Repeat Samples Required						Replacement Samples Required			
Date Analysis Begun: 10/18/17_						Time Analysis Begun: 09:25 AM			
Date Analysis Completed: 10/19/17						Time Analysis Completed: 09:55 AM			
Laboratory Log #:						Certified By:	Susan	Beasley	
COMMENTS:	Special / Non-compliance (SP), Water Source: SW, Sample Point: Routine								
	Original, Disinfectant Used: Chloramines								