N.C. Department of Environmental, Health, and Natural Resources Division of Laboratory Services State Laborabory of Public Health P.O.Box 28047 - 4312 District Drive Raleigh, NC 27611-8047 919-733-7308

DO NOT WRITE IN THIS SPACE

BACTERIOLOGICAL ANALYSIS - PUBLIC WATER SYSTEM

Laboratory ID #:	<u>37501</u>	County:	ROWAN			
Water System ID #:	01-80-771					
Name of System:	Watts BP & Grill					
Sample Type:	5 (1 = Routine; 2 = Repeat; 3 = Replacement; 4 = Plan Approval; 5 = Other)					
Collected on: DATE	10/21/15	TIME: 10:07	AM			
Location where collected	HALLWAY SINK					
Location Type:	(1 = Entry Tap	; 2 = General Tap;	3 = End Tap; 4 = S	Source/Intakes; 5 = Other)		
Location Code:	004	Collected By:	D. Wat	ts		
FOR REPEAT SAMPLE:			FOR REPLACE	MENT SAMPLE:		
Previous Positive I		Origina	al Sample Type:			
Positive Collection		(1=Routine; 2=Repeat; 3=Plan Approval; 4=Other)				
		Original Collection Date:				
Proximity:				Time		
(1 = Same; 2 = Upst	ream; 3 = Downstream)					
Mail Results To: Type of Supply:						
MOORESVILLE REGIONAL OFFICE PWSS						
610 EAST CENTER AVENUE						
MOORESVILLE, NC 28115 Type of Treatment: Chlorinated						
Telephone No.	704-663-1699			Free Chlorine Residua	l:	
EIN #: 56 60000372 AA COURIER #: 09-08-06			6	Total Chlorine Residual:		
	RESULTS			INVALID CODES		
	THOD PRESENT	ABSENT IN	VALID	1) Confluent Growth/No Coli	form Found	
	223B			2) TNTC/No Coliform Found		
Fecal/E. Coli				3) Turbid Culture/No Coliforr	m Found	
Heterotrophic P.C/ml				4) Over 30 Hours Old5) Improper Sample or Analysis		
	(number)	1			y 515	
Repeat Samples Required				Replacement Samples Required		
Date Analysis Begun:	10/22/15			Time Analysis Begun:	08:45 AM	
Date Analysis Completed	: 10/23/15			Time Analysis Completed:	09:00 AM	
Laboratory Log #:				· · · · · · · · · · · · · · · · · · ·	Beasley	
COMMENTS: Special/Non-compliance (SP), System Type: TNC, Water Source: GW						