### 4312 District Drive MSC 1918 Raleigh, NC 27699-1918

http://slph.ncpublichealth.com Phone: 919-733-7308 Fax: 919-715-8611

FINAL REPORT

Method: SM 9223B

Report to: Shawn Fox

WINSTON SALEM REGIONAL OFFICE PWSS 450 WEST HANES MILL RD STE 300

Winston Salem, NC 27105

North Carolina State Laboratory of P	ublic Health
Environmental Sciences	

Microbiology

## **Certificate of Analysis**

Name of System: Kirby's MHP

Lot# 27 - Outside spigot

EIN: 566000372X	Delivery: NC Courier	Alamance County
StarLiMS ID: ES180911-0044	Date Collected: 09/10/2018 Date Received: 09/11/2018	Time Concolod. Serve By: Chammen
Water System ID: 02-01-118 Facility ID:	System Type: C	Water Source:Ground WaterSample Type:Special/Non-Compliance
Sample Location: Outside spigot Disinfectant Used:	Location Type: Free Chlorine:	Location Code: 005 Total Chlorine:

Comments:

### PWS - Colilert Profile

Analyte	Test Result	Unit	Conclusion	Date Tested
Total Coliform	Present			09/11/2018
E. coli	Absent			09/11/2018

Report Date: 09/13/2018

Reported By: Susan Beasley

#### Explanations of Coliform Analysis:

If coliform bacteria are **Absent**, the water is considered safe for drinking purpose. If coliform bacteria are **Present**, the water is considered unsafe for drinking purpose. Presence of *E. coli* (bacteria) generally indicates that the water has been contaminated with fecal material. It must be remembered that a water analysis refers only to the sample received and should not be regarded as a complete report on the water supply.



# Apolycic