	Report Date:	06/03/2019	Reported By:	Cindy Price
Ex	cplanations of (Coliform Analysis:		

4312 District Drive MSC 1918 Raleigh, NC 27699-1918

http://slph.ncpublichealth.com Phone: 919-733-7308 Fax: 919-715-8611

FINAL REPORT

Report to: Mike Painter

WINSTON SALEM REGIONAL OFFICE PWSS

450 WEST HANES MILL RD STE 300 Winston Salem, NC 27105

EIN: 566000372X	Delivery: NC Courier	R	ockingham County
StarLiMS ID: ES190530-0121	Date Collected:05/29/2019Time Collected:Date Received:05/30/2019Time Received:	_ y -	ike Painter ngela Heybroek
Water System ID: 02-79-468 Facility ID: D01	System Type: NTNC Water Source: Sample Type:	Ground Water Source	
Sample Location: Mens restroom Disinfectant Used:	Location Type:Location Code:Free Chlorine:Total Chlorine:	MRR 0.01 mg/L	
Comments: Left sink tap			
PWS - Colilert Profile		Metho	od: SM 9223B

Analyte	Test Result	Unit	Conclusion	Date Tested
Total Coliform	Present			05/30/2019
E. coli	Absent			05/30/2019

If coliform bacteria are Absent, the water is considered safe for drinking purpose. If coliform bacteria are Present, the water is considered unsafe for drinking purpose. Presence of E. coli (bacteria) generally indicates that the water has been contaminated with fecal material. It must be remembered that a water analysis refers only to the sample received and should not be regarded as a complete report on the water supply.



North Carolina State Laboratory of Public Health

Environmental Sciences

Microbiology

Certificate of Analysis

Ellisboro Baptist Church

Name of System: