A CAN WERE	North C	Environ Mi	e Laboratory mental Scien icrobiology cate of Analy		h	Ral http Pho Fax	C 1918 eigh, NC 27699-1918 p://slph.ncpublichealth.com one: 919-733-7308 :: 919-715-8611	
Report to: Janet Mills		Name of System: United Christian Fellowship						
610 EAST CENTER AVENUE Mooresville, NC 28115				10)36 Twin	Chapel	Road	
EIN: 566000037AA		Delivery:					Rowan County	
StarLiMS ID: ES201208-003	5	Date Collected:	12/07/2020	Time Collected:	13:30	By:	Janet Mills	
		Date Received:	12/08/2020	Time Received:	07:47	By:	Denise Richardson	
Water System ID: 20-80-008	5	System Type:	NTNC	Water Source:	Ground	Water		
acility ID: D01				Sample Type:	Special/Non-Compliance			
Sample Location: 1036 Twir	Chapel Ro	Location Type:		Location Code:	200			
Disinfectant Used:		Free Chlorine:		Total Chlorine:				
Comments:								
PWS - Colilert Profile						M	ethod: SM 9223B	
Analyte	Test Result		Unit	Conclusion		Da	Date Tested	
Total Coliform	Absent						2/08/2020	
E. coli	Abse	ent				12	2/08/2020	

Explanations of Coliform Analysis:

E STATE

If coliform bacteria are Absent, the water is considered safe for drinking purpose. If coliform bacteria are Present, the water is considered unsafe for drinking purpose. Presence of E. coli (bacteria) generally indicates that the water has been contaminated with fecal material. It must be remembered that a water analysis refers only to the sample received and should not be regarded as a complete report on the water supply.

4312 District Drive