	North Carolina State				MSC 1918 Raleigh, NC 27699-1918 http://slph.ncpublichealth.com Phone: 919-733-7308 Fax: 919-715-8611	
A REAL PROPERTY AND A REAL	Enviror	ces				
What the QUAM VIDER	М					
	Certifi	cate of Analy	/sis		FI	NAL REPORT
Report to: Weston Johns	on	Name of System:				
MOORESVILLE REGIONA 610 EAST CENTER AVENUE Mooresville, NC 28115	AL OFFICE PWSS		F	ranklin	Presby	/terian Church
EIN: 566000037AA	Delivery: NC	Courier				Rowan Coun
StarLiMS ID: ES221108-0054	Date Collected:	11/07/2022	Time Collected:	12:41	By:	Weston Johnson
	Date Received:	11/08/2022	Time Received:	08:52	By:	Angela Heybroek
Water System ID: 01-80-613	System Type:	NC	Water Source:	Ground	Water	
Facility ID:			Sample Type:	Sample Type: Special/Non-Compliance		ompliance
Sample Location: Well head	Location Type:		Location Code:	E01		
Disinfectant Used:	Free Chlorine:		Total Chlorine:			
Comments:						
PWS - Colilert Profile					M	ethod: SM 9223B
Analyte	Test Result	Unit	Conclusion	Conclusion Date Tested		
Total Coliform	Absent	Absent		11/08/2022		
E. coli	Absent			11/08/2022		

Report Date: 11/09/2022

STATE

Reported By: **KPLEMMONS**

Explanations of Coliform Analysis:

If coliform bacteria are Absent, the water is considered safe for drinking purpose. If coliform bacteria are Present, the water is considered unsafe for drinking purpose. Presence of E. coli (bacteria) generally indicates that the water has been contaminated with fecal material. It must be remembered that a water analysis refers only to the sample received and should not be regarded as a complete report on the water supply.

4312 District Drive