



North Carolina State Laboratory of Public Health
Environmental Sciences
Microbiology
Certificate of Analysis

4312 District Drive
MSC 1918
Raleigh, NC 27699-1918
<http://slph.ncpublichealth.com>
Phone: 919-733-7308
Fax: 919-715-8611

FINAL REPORT

Report to: Environmental Health

Name of System:

HENDERSON CO ENVIRONMENTAL HEALTH
1200 SPARTANBURG HWY - STE 100
Hendersonville, NC 28792

William Okler
1051 Middle Fork Rd
Hendersonville, NC 28792

EIN: 566000307EH

Delivery: NC Courier

Henderson County

StarLiMS ID: **ES241119-0044** Date Collected: 11/18/2024 Time Collected: 07:30 By: William Okler
Barcode ID: 002484 Date Received: 11/19/2024 Time Received: 08:12 By: Kaila Kurtz
Sample Source: Hurricane Helene Sampling Point: Kitchen Faucet
Sample Type: GPS No.
Treatment: Chorinated Well Permit No.
Days Since Chlorine Treatment <=7 Days
Comment: Bat Cave

Colilert Profile

Method: SM 9223B

Analyte	Test Result	Unit	Conclusion	Date Tested
Total Coliform	Absent			11/19/2024
E. coli	Absent			11/19/2024

Report Date: 11/20/2024

Reported By: **KKURTZ**

Explanations of Coliform Analysis:

If coliform bacteria are **Absent**, the water is considered safe for drinking purpose. If coliform bacteria are **Present**, the water is considered unsafe for drinking purpose. Presence of *E. coli* (bacteria) generally indicates that the water has been contaminated with fecal material. It must be remembered that a water analysis refers only to the sample received and should not be regarded as a complete report on the water supply.